


## Long Scale Setup

B	Threshold	M
10 m	600-1000	4 m
16 m	1000-1300	7 m
25 m	1200-1400	7-10 m



### Notes:

1. Points 1-4 should straddle the baseline and be within 1 m of the baseline.
2. Points 5 & 6 should be about 50% of the baseline distance (B) away from the baseline.
3. Point 5 should be roughly centered in the work area and point 6 closer to Transmitter 1 (set in software) - moved parallel to the baseline.
4. The scale distance should be located parallel to the baseline, roughly centered in the work area, and 25-50% of the baseline distance (B) away from the baseline.

## Quick Setup

B	Threshold	M
10 m	600-1000	4 m
16 m	1000-1300	7 m
25 m	1200-1400	7-10 m

